

CK WORLDWIDE TIG TORCH POWER / COOLANT CONNECTORS

FITS POWER CABLES WITH A MALE THREAD 7/8"-14 LEFT HAND

If you machine has the gas flow through the female power connection then you would use the GAS-THRU Connector.





