


## SAFE-LOC CONNECTOR



GAS FLOW-THRU ONLY

FOR USE ON CK26, TL26

SL8-35M



THE SL8-35M IS A GAS FLOW-THRU CONNECTOR.

## YOU NEED TO KNOW HOW THE GAS IS GOING TO GET TO THE TIG TORCH.

 DOES YOUR MACHINE HAVE A SOLENOID AND A FLOW-THRU CONNECTION AT THE POWER CONNECTION