




SAFE-LOC CONNECTOR



GAS FLOW-THRU ONLY

FOR USE ON CK24, 80, 90, 100

SL2-25M-24



THE SL2-25M-24 IS A GAS FLOW-THRU CONNECTOR.
YOU NEED TO KNOW HOW THE GAS IS GOING TO GET TO THE TIG TORCH.

- DOES YOUR MACHINE HAVE A SOLENOID AND A FLOW-THRU CONNECTION AT THE POWER CONNECTION