



SAFE-LOC CONNECTOR

EXTERNAL GAS CONNECTION

FOR USE ON CK26, TL26

SL8-25



TYPICAL GAS HOSE CONNECTION 7/8" -14 tpi Male Connection
(THIS DOES NOT COME WITH SL8-25)



EXISTING POWER CABLE FROM THE TIG TORCH. IT CAN BE RED OR BLACK WITH A 7/8" DIAMETER EXTERNAL THREAD ON THE END



6 FOOT GAS HOSE



"B" FITTING EXTERNAL GAS CONNECTION TO
SUPPLY ARGON TO THE TIG TORCH

AW-430 "B" COUPLING IF REQUIRED



DINSE 25
(3/8" 9.5mm)

THE SL8-25 IS AN EXTERNAL GAS AND POWER CABLE CONNECTOR.

YOU NEED TO KNOW HOW THE GAS IS GOING TO GET TO THE TIG TORCH.

- DOES IT COME FROM THE REGULATOR TO THE TIG TORCH
- IS THERE A FEMALE THREADED CONNECTION ON THE WELDING MACHINE TO CONNECT THE SL8 "B" FITTING INTO
- THE SL8 ARGON HOSE IS 6 FEET LONG. IF YOUR GAS REGULATOR OR GAS SUPPLY TO THE TIG TORCH IS FURTHER, YOU MAY NEED A COUPLING AND GAS HOSE EXTENSION